

HOMOLOGATION AND TECHNICAL SPECIFICATION UPDATE BULLETIN

HOMOLOGATION	Rotax 125 Junior Max	HOMOLOGATION NO.	112H
BULLETIN NO.	Rotax 9 Junior Max	BULLETIN DATE	9 December 2016
SUBJECT	Support Plate System for Junior Max Ignition Coil		

The information and specifications contained in this Homologation and Technical Specification Update Bulletin are to be read in conjunction with and form part of the homologation detailed herein.

EXPLANATORY NOTES SUPPLIED BY THE MANUFACTURER'S REPRESENTATIVE.


Homologation Document Reference: Rotax 125 Junior Max, Rule B11.2, Page 51

Heading: Dellorto Ignition System



Details:

The new support plate system for mounting the ignition coil and magnet valve is a more compact system with less electrical connections at the backside of the engine, and the ECU now located in the battery housing. This system creates less risk of interference from any chassis components.



Support Plate System for Rotax 125 Junior MAX

(A) Mounting Plate (Part No. 651 925)

(B) Retaining Plate (Part No. 651 935)

